

HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

HAER  
TENN,  
80-CARTH.V,

1-

**Buena Vista Ford Road Bridge**

HAER No. TN-18

Spanning Round Lick Creek on McClanahan Road  
Carthage vicinity  
Smith County  
Tennessee

NOTE: Photographs were taken by George Hernal, photographer, March 12, 1985

TN-18-1	VIEW OF BRIDGE IN SETTING, LOOKING NORTHWEST
TN-18-2	VIEW OF SOUTH ELEVATION, LOOKING NORTH
TN-18-3	VIEW OF NORTH ELEVATION, LOOKING SOUTH
TN-18-4	THROUGH VIEW OF BRIDGE, LOOKING WEST
TN-18-5	THROUGH VIEW OF BRIDGE, LOOKING EAST
TN-18-6	VIEW OF WEST END, HIP PANEL, LOOKING NORTH
TN-18-7	3/4 VIEW OF BOTTOM CHORD, LOOKING EAST
TN-18-8	VIEW, LOOKING NORTHEAST, OF TOP CHORD SHOWING HIP VERTICAL ON EAST END
TN-18-9	VIEW, LOOKING NORTH, OF BOTTOM CHORD SHOWING HIP VERTICAL ON WEST END